

Agency Information

The certificate is only used for browsing on the web and proves that SETsafe | SETfuse has been certified.

If you need a FULL-VERSION certificate, please contact us: sales@SETfuse.com

该证书只用于在网页浏览，证明SETsafe | SETfuse已获得认证，如需要完整版本证书，请联系我们: sales@SETfuse.com

CERTIFICATE OF COMPLIANCE

Certificate Number 20190711-E322662
Report Reference E322662-20121227
Issue Date 2019-JULY-11

Issued to: XIAMEN SET ELECTRONICS CO LTD
8067 XIANG'AN XI RD XIAMEN TORCH
HIGH-TECH INDUSTRIAL DEVELOPMENT ZONE
XIANG'AN INDUSTRY DIST
XIAMEN
FUJIAN 361101 CHINA

**This certificate confirms that
representative samples of**

COMPONENT - SURGE-PROTECTIVE DEVICES
See Addendum Page

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: ANSI/UL 1449, Surge Protective Devices
CSA C22.2 No. 269.5-17, Surge Protective Devices – Type 5 - Component

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number 20190711-E322662
Report Reference E322662-20121227
Issue Date 2019-JULY-11

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Surge Protective Devices, Type 4 Component Assemblies

Models: SM21R2P470&, SM21R2P560&, SM21R2P680&, SM21R2P820&, SM21R2P101&, SM21R2P121&, SM21R2P151&, SM21R2P181&, SM21R2P201&, SM21R2P221&, SM21R2P241&, SM21R2P271&, SM21R2P301&, SM21R2P331&, SM21R2P361&, SM21R2P391&, SM21R2P431&, SM21R2P471&, SM21R2P511&, SM25S470P1(5), SM25S560P1(5), SM25S680P1(5), SM25S820P1(5), SM25S101P1(5), SM25S121P1(5), SM25S151P1(5), SM25S181P1(5), SM25S201P1(5), SM25S221P1(5), SM25S241P1(5), SM25S271P1(5), SM25S301P1(5), SM25S331P1(5), SM25S361P1(5), SM25S391P1(5), SM25S431P1(5), SM25S471P1(5), SM25S511P1(5), SM25S561P1(5), SM25S621P1(5), SM25S681P1(5), TFMOV10S220, TFMOV10S270, TFMOV10S330, TFMOV10S390, TFMOV10S470, TFMOV10S560, TFMOV10S680, TFMOV10S820, TFMOV10S101, TFMOV10S121, TFMOV10S151, TFMOV10S181, TFMOV10S201, TFMOV10S221, TFMOV10S241, TFMOV10S271, TFMOV10S301, TFMOV10S331, TFMOV10S361, TFMOV10S391, TFMOV10S431, TFMOV10S471, TFMOV10S511, TFMOV10S561, TFMOV10S621, TFMOV10S681, TFMOV15S220, TFMOV15S270, TFMOV15S330, TFMOV15S390, TFMOV15S470, TFMOV15S560, TFMOV15S680, TFMOV15S820, TFMOV15S101, TFMOV15S121, TFMOV15S151, TFMOV15S181, TFMOV15S201, TFMOV15S221, TFMOV15S241, TFMOV15S271, TFMOV15S301, TFMOV15S331, TFMOV15S361, TFMOV15S391, TFMOV15S431, TFMOV15S471, TFMOV15S511, TFMOV15S561, TFMOV15S621, TFMOV15S681, TFMOV15S751, TFMOV15S781, TFMOV15S821, TFMOV15S911, TFMOV15S951, TFMOV15S102, TFMOV15S112, TFMOV15S122, TFMOV20S220\$, TFMOV20S270\$, TFMOV20S330\$, TFMOV20S390\$, TFMOV20S470\$, TFMOV20S560\$, TFMOV20S680\$, TFMOV20S820\$, TFMOV20S101\$, TFMOV20S121\$, TFMOV20S151\$, TFMOV20S181\$, TFMOV20S201\$, TFMOV20S221\$, TFMOV20S241\$, TFMOV20S271\$, TFMOV20S301\$, TFMOV20S331\$, TFMOV20S361\$, TFMOV20S391\$, TFMOV20S431\$, TFMOV20S471\$, TFMOV20S511\$, TFMOV20S561\$, TFMOV20S621\$, TFMOV20S681\$, TFMOV20S751\$, TFMOV20S781\$, TFMOV20S821\$, TFMOV20S911\$, TFMOV20S951\$, TFMOV20S102\$, TFMOV20S112\$, TFMOV20S122\$, TFMOV21R2P470&, TFMOV21R2P560&, TFMOV21R2P680&, TFMOV21R2P820&, TFMOV21R2P101&, TFMOV21R2P121&, TFMOV21R2P151&, TFMOV21R2P181&, TFMOV21R2P201&, TFMOV21R2P221&, TFMOV21R2P241&, TFMOV21R2P271&, TFMOV21R2P301&, TFMOV21R2P331&, TFMOV21R2P361&, TFMOV21R2P391&, TFMOV21R2P431&, TFMOV21R2P471&, TFMOV21R2P511&, TFMOV25D220\$, TFMOV25D270\$, TFMOV25D330\$, TFMOV25D390\$, TFMOV25D470\$, TFMOV25D560\$, TFMOV25D680\$, TFMOV25D820\$, TFMOV25D101\$, TFMOV25D121\$, TFMOV25D151\$, TFMOV25D181\$, TFMOV25D201\$, TFMOV25D221\$, TFMOV25D241\$, TFMOV25D271\$, TFMOV25D301\$, TFMOV25D331\$, TFMOV25D361\$, TFMOV25D391\$, TFMOV25D431\$, TFMOV25D471\$, TFMOV25D511\$, TFMOV25D561\$, TFMOV25D621\$, TFMOV25D681\$, TFMOV25D751\$, TFMOV25D781\$, TFMOV25D821\$, TFMOV25D911\$, TFMOV25D951\$, TFMOV25D102\$, TFMOV25D112\$, TFMOV25D122\$, TFMOV25S220\$, TFMOV25S270\$, TFMOV25S330\$, TFMOV25S390\$, TFMOV25S470L(1), TFMOV25S560L(1), TFMOV25S680L(1), TFMOV25S820L(1), TFMOV25S101L(1), TFMOV25S121L(1),



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20190711-E322662
Report Reference E322662-20121227
Issue Date 2019-JULY-11

TFMOV25S151L(1), TFMOV25S181L(1), TFMOV25S201L(1), TFMOV25S221L(1), TFMOV25S241L(1), TFMOV25S271L(1), TFMOV25S301L(1), TFMOV25S331L(1), TFMOV25S361L(1), TFMOV25S391L(1), TFMOV25S431L(1), TFMOV25S471L(1), TFMOV25S511L(1), TFMOV25S561L(1), TFMOV25S621L(1), TFMOV25S681L(1), TFMOV25S470\$, TFMOV25S560\$, TFMOV25S680\$, TFMOV25S820\$, TFMOV25S101\$, TFMOV25S121\$, TFMOV25S151\$, TFMOV25S181\$, TFMOV25S201\$, TFMOV25S221\$, TFMOV25S241\$, TFMOV25S271\$, TFMOV25S301\$, TFMOV25S331\$, TFMOV25S361\$, TFMOV25S391\$, TFMOV25S431\$, TFMOV25S471\$, TFMOV25S511\$, TFMOV25S561\$, TFMOV25S621\$, TFMOV25S681\$, TFMOV25S751\$, TFMOV25S781\$, TFMOV25S821\$, TFMOV25S911\$, TFMOV25S951\$, TFMOV25S102\$, TFMOV25S112\$, TFMOV25S122\$, TFMOV34S470L(1), TFMOV34S560L(1), TFMOV34S680L(1), TFMOV34S820L(1), TFMOV34S101L(1), TFMOV34S121L(1), TFMOV34S151L(1), TFMOV34S181L(1), TFMOV34S201L(1), TFMOV34S221L(1), TFMOV34S241L(1), TFMOV34S271L(1), TFMOV34S301L(1), TFMOV34S331L(1), TFMOV34S361L(1), TFMOV34S391L(1), TFMOV34S431L(1), TFMOV34S471L(1), TFMOV34S511L(1), TFMOV34S561L(1), TFMOV34S621L(1), TFMOV34S681L(1), TFMOV34S470\$, TFMOV34S560\$, TFMOV34S680\$, TFMOV34S820\$, TFMOV34S101\$, TFMOV34S121\$, TFMOV34S151\$, TFMOV34S181\$, TFMOV34S201\$, TFMOV34S221\$, TFMOV34S241\$, TFMOV34S271\$, TFMOV34S301\$, TFMOV34S331\$, TFMOV34S361\$, TFMOV34S391\$, TFMOV34S431\$, TFMOV34S471\$, TFMOV34S511\$, TFMOV34S561\$, TFMOV34S621\$, TFMOV34S681\$, TFMOV34S751\$, TFMOV34S781\$, TFMOV34S821\$, TFMOV34S911\$, TFMOV34S951\$, TFMOV34S102\$, TFMOV34S112\$, TFMOV34S122\$, TFMOV8S220, TFMOV8S270, TFMOV8S330, TFMOV8S390, TFMOV8S470, TFMOV8S560, TFMOV8S680, TFMOV8S820, TFMOV8S101, TFMOV8S121, TFMOV8S151, TFMOV8S181, TFMOV8S201, TFMOV8S221, TFMOV8S241, TFMOV8S271, TFMOV8S301, TFMOV8S331, TFMOV8S361, TFMOV8S391, TFMOV8S431, TFMOV8S471, TFMOV8S511, TFMOV8S561, TFMOV8S621, TFMOV8S681

suffix \$ may be f/b B, G, M, or H, may be followed by -IT.
suffix & may be followed by -P
suffix (1) may be f/b -IT
suffix (5) f/b NBA or NBB



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>

